




KITCHEN SCALE

RM/299



User Manual

1) Technical data

- 1. maximum capacity: 5000g
- 2. weight graduation: 1g
- 3. minimum capacity: 2g
- 4. weight tolerance: $\pm 0.3\%$

2) Function keys



3) Directions for use

1. Power-on



Pull out the insulation sheet from the battery compartment in the indicated direction.

2. operation environment





The scale should be placed on a firm and level platform.

3. Tare


(1)



Press the button “” to switch on the scale and put the tank on the platform. Press the button “” again to eliminate the weight of the tank, LCD displays zero at last..


(2)



It also can be done by putting the tank on the platform before press the Button “” to switch on the scale.


4. Weighing



Put the object to be weighed in the tank or on the scale, you can read the weight immediately. Take out the things, the scale will reset to zero automatically and the next measurement can be done. The scale will shut off automatically in 2 minutes if no weighing detected, and it also can be shut off by pressing the button “”.

5. Choosing unit



When turning on the scale, press the button “” to select the weight unit .


4) Precautions

1




Low battery volt replace with a piece of new batteries (CR2032).

2



Avoid overloading, the total weight of the tank and the item in it should not exceed 5kg. Otherwise the scale will possibly be damaged.

3



Batteries should be removed from the battery compartment if the scale will not be used for a long period of time.